Subpart Z Process Unit Information for Units NOT Monitored by CEMS for RY2014 and Later

This page provides step-by-step instructions on how to enter and edit Subpart Z Phosphoric Acid Manufacturing process unit information.


Step 1: Add a unit


To add a unit that is NOT monitored by a CEMS, find the WET-PROCESS PHOSPHORIC ACID LINES (Lines not monitored by CEMS) table on the Subpart Overview page and click the link titled "ADD a Unit".

To edit a unit, click the edit icon or the Name/ID link located in the first column of the table.

To delete a unit, click the delete icon located in the last column of the table.

>> Click this link to expand





Step 2: Confirm that CEMS are not utilized for this unit


For each process unit, confirm whether or not the process unit utilizes CEMS.


Note that when adding a new unit you are prompted to answer the CEMS question immediately (the answer to this question will default to "No" for units added using the "ADD a Unit" link and will default to "Yes" for units added using the "ADD a Unit Monitored by CEMS" link).

The CEMS response may be changed here and the unit information will be relocated to the appropriate table on the Subpart Overview page.

When finished, click SAVE.

>> Click this link to expand






Step 3: Enter required information for a unit

For each process unit at your facility, report the following required information:


- · A unique name or identifier for the unit, plus optional description for this facility (see also About Unique Unit Names)
- Calculation Method Used (Eq. Z-1a or Eq. Z-1b)
- Annual Phosphoric acid production capacity for the unit

When finished, click SAVE



e-GGRT RY2013.R25 | Z(procLine)


Paperwork Reduction Act Burden Statement | Contact Us




Step 4: Enter the Phosphate Rock Origin for a unit

Error rendering macro 'excerpt-include'

No link could be created for 'Entering Phosphate Rock Origin'.





Step 5: Repeat Steps 1-4

Repeat Steps 1-4 until all process units and phosphate rock origins for each unit have been added for your facility.

Back to Top

See Also

Screen Errors

Using e-GGRT to Prepare Your Subpart Z Report for RY2014 and Later

- Subpart Z Emissions Information for Process Units Monitored by CEMS for RY2014 and Later
 Subpart Z Emissions Information for Process Units NOT Monitored by CEMS for RY2014 and Later
 Subpart Z Entering Equation Inputs Using IVT
 Subpart Z Facility-Level Information for RY2014 and Later
 Subpart Z Process Unit Information for Units Monitored by CEMS for RY2014 and Later
 Subpart Z Process Unit Information for Units NOT Monitored by CEMS for RY2014 and Later
 Entering Phosphate Rock Origin for RY2014 and Later